

| Team                            | Number | Penalty type                        | Reason                                              | Time             | Points |
|---------------------------------|--------|-------------------------------------|-----------------------------------------------------|------------------|--------|
| BRS Motorsport                  | E45    | SES/ASES                            | Incomplete ASES 2x                                  | 08.08.2025 10:57 | 20     |
| UWB eRacing Team Pilsen         | E2     | SES/ASES                            | Late submission SES 5x, incomplete ASES 2x          | 08.08.2025 10:57 | 70     |
| Formula Student Team Weingarten | E60    | SES/ASES                            | Late submission SES 1x                              | 08.08.2025 10:56 | 10     |
| CURE Mannheim e.V.              | E71    | Media Vest misuse                   | Media vest                                          | 08.08.2025 9:34  | 10     |
| HofSpannung Motorsport e.V.     | E86    | Non-compliance                      | Non compliance car                                  | 07.08.2025 20:44 | 20     |
| Centaurus Racing Team           | E77    | TSMS not locked overnight (EV6.2.2) | TSMS not locked overnight (EV6.2.2)                 | 07.08.2025 9:37  | 10     |
| BRS Motorsport                  | E45    | Non-compliance                      | Monocoque EI equivalence needed                     | 06.08.2025 17:25 | 100    |
| BRS Motorsport                  | E45    | Non-compliance                      | 5mm Rim clearance                                   | 06.08.2025 17:23 | 20     |
| E-Motion Rennteam Aalen         | E61    | No vest in dynamic area             | Team members in dynamic area without dynamic vests. | 05.08.2025 18:21 | 10     |
| Rennschmiede Pforzheim          | E79    | Non-compliance                      | Wheel studs                                         | 05.08.2025 13:53 | 20     |
| Zürich UAS Racing               | E16    | Non-compliance                      | FBHS Tube triangulation                             | 05.08.2025 11:49 | 20     |
| AGH Racing EV                   | E30    | No vest in dynamic area             | Team members in dynamic area without dynamic vests. | 05.08.2025 10:17 | 10     |
| Revolve NTNU                    | E63    | Non-compliance                      | Rim clearance                                       | 05.08.2025 9:50  | 20     |
| Formula Student Team Weingarten | E60    | Non-compliance                      | SES Harness sample                                  | 05.08.2025 9:49  | 20     |
| High-Voltage Motorsports e.V.   | E94    | Non-compliance                      | MH outer diameter                                   | 04.08.2025 16:27 | 20     |
| PWR Racing Team                 | E15    | Non-compliance                      | AIP untested                                        | 04.08.2025 15:26 | 20     |
| Mainfranken Racing e.V.         | E97    | No vest in dynamic area             | No vest in dynamic area                             | 04.08.2025 12:50 | 10     |
| Formula TU Ostrava              | C89    | SES/ASES                            | Late submission SES 3x                              | 08.08.2025 10:59 | 30     |
| Tampere Formula Student         | C78    | Non-compliance                      | SES orientation                                     | 05.08.2025 14:47 | 20     |