

Official results

Version: 1.0 · Publication date: 2026-07-28

Team	Number	Penalty	Points	Reason
AAU Racing	E18	EV 6.2.2 violation - TSMS lockout	20	TS Master switch is in the car after closing of the pits
AGH Racing EV	E35	Last Warning	0	HVD present on car after closing of the pits without having passed HV electrical inspection.
ARUSe	E92	Last Warning	0	Not properly locked master switches after closing of the pits. The key for the lock is still inside the lock.
ARUSe	E92	Parts from car in the campsite	100	Following the completion of the mechanical inspection, the team proceeded to remove components from the vehicle without prior approval and continued working on the car in the campsite during nighttime hours. As a result, a penalty of 100 points has been applied, and the previously granted mechanical inspection approval has been revoked.
ARUSe	E92	Late Completion of Technical Inspection - DV	100	Wednesday inspection
BCN eMotorsport	E54	Non-compliant dynamic cart	25	Non compliant dynamic cart
BCN eMotorsport	E54	Late Completion of Technical Inspection - DV	100	Wednesday inspection
Bodensee Racing Team	E43	No vest in dynamic area	10	Without vest in dynamic area. Photo taken in ACU tent as he didn't even have the name tag on his neck.
Bremergy e.V.	E72	No vest in dynamic area	10	No dynamic vest
CAT-Racing	E70	Media Pass holder assisting a team in the Dynamic Area	10	Media guy assisting team in the dynamic area. Media vest removed.
CURE Mannheim e.V.	E69	VSV late submission	10	Late submission of VSV
DHBW Engineering Stuttgart e.V.	E7	T4.2 violation	20	T4.2 violation
Dynamics UPC Manresa	E25	IAD Late Submission	10	IAD Late Submission to FSG Portal

Team	Number	Penalty	Points	Reason
e-gnition Hamburg e. V.	E78	T2.6.4 violation - wheel 5mm clearance	20	Rim clearance
Ecurie Aix Formula Student Team RWTH Aachen	E99	Last Warning	0	HVD present on car after closing of the pits without having passed HV electrical inspection
Ecurie Aix Formula Student Team RWTH Aachen	E99	Late Completion of Technical Inspection - DV	100	Wednesday inspection
EFORCE Prague Formula	E42	No vest in dynamic area	10	Team member in the dynamic area without vest.
EFORCE Prague Formula	E42	Non-compliant dynamic cart	25	Things falling out of the cart
EFORCE Prague Formula	E42	A/SES Late Submission	10	University Name,Number of Instances,Instances: Prague CTU,1,2026-06-05 12:08->2026-06-12 16:34 (172.4h)
FaSTDa Racing	E24	Non-compliant dynamic cart	25	Things falling out of the dynamic cart
FESB Racing	E44	EV 6.2.2 violation - TSMS lockout	20	Missing lock on TSMS during the night.
FESB Racing	E44	Media Pass holder assisting a team in the Dynamic Area	10	Media assisting team.
High-Voltage Motorsports e.V.	E94	EV 6.2.2 violation - TSMS lockout	20	TS Master switch is in the car after closing of the pits
High-Voltage Motorsports e.V.	E94	EV 6.2.2 violation - TSMS lockout	20	No lock on master switch
KA-RaceIng	E76	SES - T3.5.3 violation	25	Penalty points according to IN1.2.8 for rule T3.5.3 violation
KTH Formula Student	E71	No vest in dynamic area	10	No vest in dynamic area
Lund Formula Student	E46	VSV late submission	10	Late submission of VSV
PRz Racing	E8	DD late submission	10	Late driver designation
PRz Racing	E8	A/SES Late Submission	10	University Name,Number of Instances,Instances: Rzeszów TU,1,2026-05-21 09:03->2026-05-28 22:49 (181.8h)
PRz Racing	E8	Rejected protest	25	Rejected protest

Team	Number	Penalty	Points	Reason
PWR Racing Team	E16	A/SES Late Submission	10	University Name,Number of Instances,Instances: Wroclaw TU,1,2026-06-16 20:03->2026-06-23 20:25 (168h)
Raceyard E	E53	IAD Late Submission	10	IAD Late Submission to FSG Portal
Rennteam Uni Stuttgart	E29	Unsportsmanlike Conduct	25	During the Endurance event, the team demonstrated unsportsmanlike conduct by refusing to allow the event scrutineers to inspect the vehicle and by repeatedly arguing with event officials. This behaviour obstructed the officials in performing their duties and was not consistent with the expected standards of cooperation and respect at Formula Student Czech Republic.
Road Arrow	E30	EV 6.2.2 violation - TSMS lockout	20	TS Master switch is in the car after closing of the pits
StarkStrom Augsburg	E17	CRD late submission	10	Late submission of CRD
StarkStrom Augsburg	E17	Withdrawal from Dynamic Events	0	The team has withdrawn from all dynamic events because the vehicle is not operational. The team is permitted to complete the technical inspection for educational purposes only. No penalty points are assigned.
Superior Engineering FS Ljubljana	E68	Media Pass holder assisting a team in the Dynamic Area	10	Media guy assisting team in the dynamic area. Media vest removed.
Superior Engineering FS Ljubljana	E68	A/SES Late Submission	10	University Name,Number of Instances,Instances: Ljubljana U,1,2026-06-06 16:17->2026-06-13 20:34 (172.3h)
Tecnun eRacing	E14	TVSD late submission	10	Late submission of TVSD
UGent Racing	E51	Last Warning	0	HVD present on car after closing of the pits without having passed HV electrical inspection.
UMD Racing e.V.	E20	TVSD late submission	10	Late submission of TVSD
UWB eRacing Team Pilsen	E2	IAD Late Submission	10	IAD Late Submission to FSG Portal
WHZ Racing Team	E96	A/SES Late Submission	10	University Name,Number of Instances,Instances: Zwickau UAS,1,2026-04-16 21:08->2026-04-25 03:40 (198.5h)
YTU Racing	E34	Media Pass holder assisting a team in the Dynamic Area	10	Media guy assisting team in the dynamic area. Media vest removed.